

Gen1 Open Source Hand Work Instruction

by  TetherIA

Useful Tools

Tools:

1mm drill bit
2mm drill bit
2.1mm drill bit
Hand drill
Exacto Knife
Flash Cutters
File
Soldering Iron
Needle Nose Pliers
Phillips Driver
Torx Driver
Measuring Tape
Marker
Scissors


Consumables:

Super Glue
Loctite (blue 496)



Optional:

Silicone 2part
Hot Glue
Finger Tip Silicone Cover
Protoboard
22awg solid core wire
Reset tactile button
Solder Flux
Solder
Hot Glue Gun
Heat Insert Tip
Molex 3pin female Connector
Palm Foam
Sandpaper

3D Printed Parts



PN	Name	QTY
01	Finger Base	4
02	Finger MCP	4
03	Finger Proximal	4
04	Finger Medial	4
05	Finger Distal	4
10	Thumb CMC Base	1
11	Thumb MCP	1
12	Thumb Proximal	1
13	Thumb Distal	1



PN	Name	QTY
14	Servo Frame	1
15	Palm Front Frame	1
16	Palm Rear Frame	1

3D Print Cleanup


- Tools:**
File
Sandpaper
Flash Cutter
Hand Drill (1mm, 2mm, 2.1mm)


Name	Part Number	QTY
Finger Base	1	4
Finger MCP	2	4
Finger Proximal	3	4
Finger Medial	4	4
Finger Distal	5	4
Thumb CMC Base	10	1
Thumb MCP	11	1
Thumb Proximal	12	1
Thumb Distal	13	1
Servo Frame	14	1
Palm Front Frame	15	1
Palm Front Frame	16	1

Debur 3D Printed Components

Use a flush cutter to remove the supports. Then, use a file or sandpaper to deburr the printed parts.

Pictures with positions indicated by arrows need special attention to ensure proper part function.







Drill



1. Drill out holes in finger joints for all four fingers




Note: All holes are through holes




Drill

- 1. Drill out holes in thumb joints
- Note: All holes are through holes unless otherwise stated



	2.1 mm
	2.0 mm
	1.0 mm



Cable


Pre-assembly

Tools:
Scissors
Measuring Tape


Name	ServoID #	QTY	Total Length (mm, from knot)	Marked Length (mm from spool exit)
Finger Pull Cable	3,4,5	3	300	140
Pinky Pull Cable	6	1	300	150
Finger Coupling Cable	NA	4	300	None
Thumb CMC Flex Cable	1	1	300	90
Thumb Pull Cable	2	1	300	150
Thumb Coupling Cable	NA	1	300	None

1. Tie ashley stopper knot on the end of vectran spool


Ashley Stopper Knot Instructions



2. Cut vectran 300mm from knot
3. Repeat 10 more times, creating a total of 11 cables



4. Trim the tail of the ashley stopper knot to <5mm
for all cables



Finger Assembly



Tools:
Threading Tool
Pliers
Torx Driver

Name	Part Number	QTY
Finger Base	1	4
Finger MCP	2	4
Finger Proximal	3	4
Finger Medial	4	4
Finger Coupling Cable	26	4
UNDERSIZED 2x10 Pin	32	16
2x5x2.5 bearing	30	16
1x10 Pin	31	12
M2x6 Flanged Torx Self Tapping Screw	38	4
Finger Proximal/MCP Return Spring	22	4
Finger Distal/Medial and Thumb Proximal/Distal Return Spring	21	4

Bearings



1. Place four bearings (30) in finger proximal (3) and finger base (1) components
2. Secure using 2x10mm pins (32)
3. Repeat for all fingers

NOTE: Ensure all bearings spin, if not file/sand/deburr plastic



Finger Coupling Cable

4. Route a non-marked cable through hole at end of Finger proximal piece
5. Pull tight once routed to pretension/remove any slack that could be present in the ashley stopper knot







6. Install spring (21) connecting proximal (3) and medial (4) components using two 1x10mm pins (31)

7. Install spring (22) on base of proximal using one 1x10mm pin (31)

8. Connect proximal and medial sections using one 2x14mm pin (34)

9. Thread coupling cable through bottom hole on medial section











10. Route coupling cable underneath the bar on the distal section

11. Wrap coupling cable around bar once. Ensure that the cable wraps

12. Start to thread M2x6 Torx screw (38) into the distal section

13. connect distal and medial with 2x14mm pin






13. Pull cable taut

14. Flex finger while maintaining tension

15. Tighten screw until cable is securely pinched

16. Distal/medial and medial/proximal angle should maintain the same angle when opening/closing the finger. See video

17. Repeat from step 1 for three remaining fingers





Thumb Assembly

Tools:
Threading Tool
Pliers
Torx Driver
Loctite

Name	Part Number	QTY
Thumb Abduction Upper Servo Disk	7	1
Thumb Abduction Lower Servo Disk	8	1
Thumb Abduction Linkage Bar	9	1
Thumb CMC Base	10	1
Thumb MCP	11	1
Thumb Proximal	12	1
Thumb Distal	13	1
Finger Coupling Cable	26	1
UNDERSIZED 2x10 Pin	32	5
2x5x2.5 bearing	30	5
1x10 Pin	31	2
M2x6 Flanged Torx Self Tapping Screw	38	1
Finger Distal/Medial and Thumb Proximal/Distal Return Spring	21	4
2x10 Pin	33	1
Servo Motor Mount Plate	43	1
Servo Motor Spline Screw M2.3x5	44	6
Servo Motor Plate Screw M2x4	45	1
Thumb CMC/MCP Return Spring	23	1


Thumb Bearings

1. Insert bearings into thumb base (10) and thumb MCP (11)
2. Secure using undersized 2x10mm pins (32)



Thumb Assembly



1. Attach spring (21) with 1x10mm pin (31) to proximal
2. Attach other side of spring to MCP using 1x10pin (31)
3. Attach distal, proximal and MCP with 2x20mm pins (36)



3. Connect thumb MCP to CMC using thumb spring (25) and two 1x10mm pins



4. Insert CMC into MCP. Add bearing between components

5. Secure using 2x20mm pin



Thumb Coupling Cable

8. Thread a cable through in MCP
9. Pull taut
10. Thread through lower hole in proximal and over distal
11. Add loop on crossmember. Note direction of loop
12. Tension and secure same as fingers with 2x6mm torx screw (38)



Servo ID and Assembly

Tools:

Computer
Breadboard
Marker
Molex Connectors
Soldering Iron
Protoboard

Name	Part Number	QTY
Servo Motor	42	7
Cable Spool	6	6
Finger Pull Cable	24	4
Pinky Pull Cable	25	1
Thumb CMC Flex Cable	27	1
Thumb Pull Cable	28	1
Servo Motor Mount Plate	43	6
Servo Motor Spline Screw M2.3x5	44	18
Servo Motor Plate Screw M2x4	45	6
Connection Cable	47	1

Linkage Assembly

1. Place aluminum disk (43) into thumb servo lower disk (7). Secure using M2x4 screws (45) with loctite
2. Add thumb servo upper disk (8) piece sandwiching the aluminum. Secure using M2x4 screws with loctite
3. Drill linkage holes in disks with 2mm drill (7 and 8)
4. Drill linkage hole in linkage bar with 2.1mm drill (9)
5. Place linkage bar between disks and secure using 2x10 pin (33). Note: direction of linkage is important. Reference image



Label Servos


1. Label all 7 servos with a sharpie or paint marker with a unique number:
0, 1 ,2, 3 ,4, 5, 6

Reference image for location of
number



Power Supply Connector

1. Cut and strip existing terminal off end of cable (6vdc power supply)
2. Solder ends onto xt30 connector. Note: Flat side of xt30 connector is positive
3. Add heat shrink tube to cover exposed wires




Control Board

(not needed if PCB purchased)


Build a control board using the electrical schematic

Board can be built on a breadboard (no soldering required), custom PCB or protoboard




Example protoboard

GREEN - RX
YELLOW - TX
BLACK - GROUND




Program Servos

3. Connect power (6vdc) to control board and esp32 to computer
4. https://docs.tetheria.ai/docs/getting_started/#setting-servo-ids
5. Follow steps to program and set ID for each servo



or



Servo Spools


6. Screw cable spool (6) into aluminum servo mount (43) using three screws (45). Apply loctite to threads before installing

7. Attach mount to servo using large screw (44) and loctite

8. Thread a cable into servo

9. Mark length based on servo number (example: servo #1 = length 90mm)

10. Repeat for servos 1, 2, 3, 4, 5 and 6



Thread finger servo cable

10. Install servo base and MCP onto finger proximal using 2x14mm pin






11. Thread the servo 6 cable through a finger base

12. Thread between bearings on distal

13. Thread through top medial hole and distal

14. Tie ashley stopper knot at mark

15. Repeat for servos 3, 4, and 5



Servo Busbar

(not needed if PCB purchased)

16. Cut 7x8 protoboard


17. Place molex connectors as in image. Note orientation.

18. Solder together using 22awg solid wire as in image

19. Clean board to remove residual flux

20. Cover wires in hot glue or liquid electrical tape to protect against electrical shorting

NOTE: This step can be skipped by simply daisy chaining the servos together using the 3-way connects supplied with the servos






Hand Base

Tools:
Soldering Iron
Torx Driver
Philips Driver

Name	Part Number	QTY
Servo Frame	14	1
Palm Front Frame	15	1
Palm Rear Frame	16	1
M3x6.4 Heat set insert	41	4
M2x10 Countersunk Torx Self Tapping Screw	39	12
M2x6 Flanged Torx Self Tapping Screw	38	14
2x20 Pin	36	1
UNDERSIZED 2x30 Pin	37	1


Threaded Heat Inserts

1. Warm up a soldering iron with a heated insert tip
2. Gentle apply force on the heat insert using the iron
3. Make insert flush with surface of print, repeat for all 4 inserts



Servo Frame

1. Place servo 1 onto servo frame (14) and secure with two M2x6 self tapping screws (38)
2. Place servo 0 onto frame and secure with four M2x6 self tapping screws
3. Place servo 2 onto frame and secure with two M2x6 self tapping screws
4. Add linkage to servo 0 using screw (provided with servo) with loctite



Servo Frame Install

Insert 2x10 pin (34) between servo linkage
and thumb CMC base (10)



Install Finger Servos

1. Place servos 3, 4, 5, and 6 in back palm with number visible


2. Add frame with servos 0, 1, and 2. Feed wires from servos 1 and 2 under other servos

3. Secure MCP blocks using M2x10 countersunk screws

4. Connect all servo wire connectors to PCB female connectors



5. Push PCB in palm, align notch with hole on palm. Secure using M2x10 (39) screws

Note: for left hand, reverse servo sides



Install Finger Servos



1. Push frame onto palm
2. Make sure frame contacts palm without requiring excessive force. This step may take time to ensure no wires are crushed
4. Secure frame using M3x10 screws



MCP Springs



1. Secure fingers with M2x10 (39) screws
2. Secure MCP springs (22) to rear palm using 2x6 self tapping torx (38)

Note: Do not fully tighten screws to avoid permanent deformation of springs





Thumb CMC Flex Cable

1. Thread cable from servo 1 as seen in image
2. Thread through hole closer to back of palm on thumb MCP (11)
3. Tie ashley stopper knot at mark
4. Pull string tight



Thumb Pull Cable

1. Thread cable from servo 2 as seen in image
2. Thread through MCP (10) around bearing
3. Thread through top hole in thumb proximal (12)
4. Tie ashley stopper knot at mark and pull tight




Thumb Bearings

25. Insert bearings (30) into CMC base and push in as far in as possible



26. Insert 2x30mm pin (37) from bottom until it is flush with the top surface

Note: applying pressure on bearings while installing pin will ensure they don't fall out



Front Palm

1. Secure servos 3,4,5, and 6 servos to frame using 2x6 self tapping torx screws (38)
2. Add front palm
3. Secure with four 3x10 self tapping screw on back of hand
4. Trim all cables 5mm from knot



Final Touches

Tools:
Hot Glue
Super Glue

Name	Part Number	QTY
Palm Foam	20	1
3x10 self tapping	40	9
2x6 self tapping	36	8
M2x10 Countersunk Torx Self Tapping Screw	39	12
M2x6 Flanged Torx Self Tapping Screw	38	14
UNDERSIZED 2x30 Pin	37	1
Connection Cable	47	1
TTLinker	48	1

Silicone Inserts Molds (optional)

1. Place 3D printed molds on a flat/hard surface. Placing on a baking tray or sheet of aluminum will make cleanup easier.



2. Mix a batch of silicone using instructions on bottles. 40grams total is enough to make one set of parts for a hand.

3. Fill mold negatives ~80%. Let sit for 5minutes to allow bubbles to escape.

4. Add top half of mold to bottom half for distal and proximal molds. Push until flush. Silicone should leak out if filled correctly.


5. Let sit upright for 3h, until fully cured. Then separate silicone from molds.

6. Remove flash from edges of components



Silicone Inserts (optional)

7. Apply silicone adhesive to internal side of distal and proximal components
8. Spread around to create a uniform layer on the plastic
9. Gently press on foam and hold for 30seconds, until glue solidifies
10. Repeat for all fingers and thumb



Silicone Inserts (optional)


11. Apply even/thin layer of silicone adhesive to plastic. Spread to edges of offset surface.

12. Put on silicone pad to palm and gently apply force for 30seconds to allow to glue to cure



High Cycling Protection (optional)

24. If using for high cycling >10,000 cycles per joint, apply superglue to every pin on both sides. This will secure them from sliding out.



Congratulations, you made it!

Your Aero hand is ready to meet the world. Let us know what you think of the hand.

<https://tetheria.ai>

